

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	50	("6556908") or ("6718248") or ("5890084") or ("5797111") or ("6654674") or ("6671595") or ("6005492") or ("6684140") or ("6804584") or ("6169946") or ("6263261") or ("6324446") or ("6332104") or ("6338012") or ("6496758") or ("6529803") or ("6799092") or ("6834218") or ("4371191") or ("4869528") or ("4949262") or ("5684698") or ("4400008") or ("4456282") or ("4457536") or ("4458918") or ("4458913") or ("4480852") or ("4575116") or ("4834419") or ("5422810") or ("5762157") or ("6405132") or ("6424907") or ("6438464") or ("5762351") or ("6631317") or ("6782315") or ("4796720") or ("4372407") or ("4887829") or ("5540454") or ("6263994") or ("6725140") or ("6065558") or ("4927173") or ("6397127") or ("6593849") or ("6830256") or ("5505482")).PN.	USPAT	OR	OFF	2005/06/14 07:57
L2	28	("4970653" "5208750" "5301115" "5351044" "5379353" "5517412" "5555312" "5617085" "5642093" "5661472" "5684697" "5765116" "5790403" "5892855" "5913375" "5926126").PN. OR ("6005492").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/06/14 08:35

L3	49	(".(4887840") or ("5718445") or ("5820156") or ("5882031") or ("4903982") or ("4930082") or ("4345661") or ("4361346") or ("4482939") or ("4625993") or ("4856798") or ("4897776") or ("4927170") or ("5239868") or ("4357033") or ("4805929") or ("4826141") or ("4867475") or ("4890858") or ("4892503") or ("4909534") or ("4924393") or ("4948164") or ("5016908") or ("5020825") or ("5195772") or ("5217246") or ("5232242") or ("5291406") or ("5475593") or ("5510986") or ("5555501") or ("5653315") or ("6016120") or ("6029764") or ("6175792") or ("6138066") or ("6202011") or ("4313616") or ("4844506") or ("4854603") or ("4927169") or ("5372377") or ("5435591") or ("5549328") or ("5948027") or ("6086071") or ("3913938") or ("4278854") or ("4434998")).PN.	USPAT	OR	OFF	2005/06/14 08:38
L4	61024	(camera video ccd imag\$3) and (roll\$3 rollover overturn\$3 tip\$5 tilt\$3) and (vehic\$3 car mobile automo\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/14 08:39
L5	2157	(camera video ccd imag\$3 optical) and (roll\$3 rollover overturn\$3 tip\$5 tilts\$3) and (vehic\$3 car mobile automo\$4) and imag\$3 and yaw\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/14 08:40
L6	131	5 and stereo near3 (imag\$3 camera optic\$6 ccd)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/14 08:40
L7	23	("4016566" "4340299" "4713665" "4728954" "4893287" "4942558" "4942765" "4961643" "4990791" "5054003" "5097453" "5100230" "5148409" "5239516" "5287329" "5475620" "5491648" "5621413" "5621514" "5696515" "6230107" "6285938" "6445338").PN. OR ("6885968").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/06/14 08:49
L8	27	("3873964" "4348652" "4401181" "4800978" "4970653" "5153525" "5347456" "5357432").PN. OR ("5708427").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/06/14 08:55

L9	26	("4373161" "4530056" "4582159" "4691284" "4695068" "4847773" "4932617" "4949261" "5093790" "5275253" "5289895" "5318143" "5369591" "5373911" "5448479" "5481268" "5485378" "5698259" "5708427" "5774069").PN. OR ("5906645").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/06/14 09:03
L10	601	4 and rollover	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/14 09:08
L11	126	10 and yaw\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/14 09:08
L12	118	11 not 6	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/14 09:20
L13	3989	("701"/\$ "340"/\$ "180"/\$ "280"/\$). ccls. and 4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/14 09:22
L14	179	13 and (front aft\$3 rear behind back) near3 (camera video imag\$3 optic\$5 ccd) and side near3 (camera video imag\$3 optic\$5 ccd)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/14 09:27
L15	18	("5515419" "5664227" "5731757" "5867103" "5892855" "5894323" "6054928" "6067110" "6072396" "6083353" "6100806" "6118475" "6151539" "6154149" "6172601"). PN. OR ("6535114").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/06/14 09:45